

N65928.AR.002377  
NTC ORLANDO  
5090.3a

LETTER AND COMMENTS FROM FLORIDA DEPARTMENT OF ENVIRONMENTAL  
PROTECTION REGARDING OIL WATER SEPARATOR ASSESSMENT REPOTS BUILDINGS  
354 AND 2078 NTC ORLANDO FL  
7/14/1997  
FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION

747.08545


# Department of Environmental Protection

Lawton Chiles  
Governor

Twin Towers Building  
2600 Blair Stone Road  
Tallahassee, Florida 32399-2400

Virginia B. Wetherell  
Secretary

July 14, 1997



Mr. Nick Ugolini  
Code 184(PVC)  
Southern Division  
Naval Facilities Engineering Command  
2155 Eagle Drive  
P.O. Box 190010  
North Charleston, South Carolina 29419-9010

RE: Oil Water Separator Assessment Reports (OWSARs), Buildings  
354 and 2078, Naval Training Center, Orlando, Florida


Dear Mr. Ugolini:

I have completed the technical review of the above referenced reports dated June 1997 (received June 16, 1997). Based upon the sampling and analysis, no further investigation is needed for the oil water separator at Buildings 2078.

Further groundwater analysis is needed at Building 354 due to exceedances of the Florida Groundwater Guidance Concentrations for chloroform and bromodichloromethane. Additional sampling and analysis of the groundwater is necessary unless the assumption can be proven by the laboratory that these compounds were detected due to laboratory-introduced contamination. Analysis is only needed using EPA Method 624/8240.

If I can be of any further assistance with this matter, please contact me at (904) 921-9989.

Sincerely,

  
John W. Mitchell  
Remedial Project Manager

cc: Wayne Hansel, Navy SouthDiv  
Lt. Gary Whipple, NTC Orlando  
John Kaiser, ABB Orlando  
Steve McCoy, Brown and Root, Oak Ridge  
Bob Cohose, Bechtel, Knoxville  
Nancy Rodriguez, USEPA Region 4  
Bill Bostwick, FDEP Central District

TJB B

JJC B for JC

ESN ESN